

## EVO Dehumidifier Additional information per Board Request:

PoolPak 5WHP 140-08E-B06 Rooftop Unit and matching PoolPak BRH041 Air Cooled condenser.

The \$2,664.07 only includes: The work necessary to determine what work will be needed. At this time in the current condition, it cannot be evaluated. This work will be remedial and is required before the evaluation can be completed, as follows: All compressor breakers were found in the "OFF" position and there are several alarms in the system controller module. All the electrical connections need to be checked, cycle the power to the compressors, check operations (pressures, temperatures, check faults in the controller module and document any findings). Once completed, any additional repairs needed will be quoted.

This is the cost for 2 days' work for a Journeyman Service Technician to do intensive troubleshooting of the unit.

After the initial \$2,664.07 is spent the dehumidifier will not work. This money is just for troubleshooting, NESM has suspicions that there are problems with control boards, and they do not know why the compressors were taken offline.

Also, I misunderstood what they had stated during the meeting regarding the Poolpak units, and it was the other two dehumidifiers in the exercise rooms (DU-1/RCU-1 and DU-2/RCU-2 PoolPak units) that they do not make anymore and there are no replacement parts. Not the Poolpak unit for the Pool area.